



1

For traceability, an RMA label is required for each unit returned for repair. To obtain a label, please contact the technical support team on 01159 640144 or email them at [technical\\_support@uk.interactivecoding.com](mailto:technical_support@uk.interactivecoding.com) with your fault and serial number to hand.

2

Print the RMA label and package your equipment suitably for shipping. Please apply the label to the outside of the box so that the RMA label is clearly visible.

3

Send it back to us:  
Olympic House, 1 Willow Drive,  
Sherwood Business Park, Annesley,  
Nottinghamshire, NG15 0DP



4

We will email you to confirm receipt of your equipment on the day of arrival. Once our engineer has carried out the evaluation of the unit, we will send an itemised breakdown of the costs including parts, carriage and labour.


5

Once we have your authorisation, we will carry out the required work. We will then email you a copy of the completed repair report and confirm your delivery date. Any spares or consumables items you require can also be sent out at the time, providing an opportunity to save on carriage charges.

i

Please note: We will hold equipment awaiting authorisation on site for up to 3 months, after this time it will be returned unrepaired and carriage will be invoiced.

RMA label



**Repairs**

Clearmark Solutions Ltd.  
OLYMPIC HOUSE  
Olympic House, 1 Willow Drive,  
Sherwood Park, Nottingham,  
NG15 0DP

RMA Number:	10015
ICE Contact Name:	Richard Flair
Return Type:	Inhouse Repair
Item:	Zodiac Plus, LH HS, 53mm - Part No: 405706
Serial Number:	
Action Required:	
Customer Name:	RMA (Chargeable)
Contact Name:	Veggie World
Return Address:	Joe Bloggs
Alternative Address:	1 Carrot Close Turnipton Lettuce
Additional Information:	Inhouse Repair

Repair evaluation form



**Repairs**

Zodiac Hawk Evaluation Form

Company Name	Reported Fault	Machine Type	Serial No Printer/Scanner	Serial No Cassette	Assure Status	Software Version I	Mode	Ribbon Used	RMA
									Date
									E Technician
									R Technician
									Belt Tension
									Head to Platen Gap
									Printhead S/N
									Software Version O
									Location
									Archive/Clone Task

Engineer Comments & Parts Required

Item Code	Description	Qty	Price
36004	Labour	1	£0.00
28001	Carriage		£15.00
	<b>Total</b>		£15.00

Need some help? 01159 640144

